



This report provided free of charge by:

Victory Auto Sales, LLC
 4885 Elmore Rd, Memphis, TN 38128
 (901) 380-5800



Vehicle History Report™

US \$39.99

2013 NISSAN ALTIMA 2.5/S/SV/SL

VIN: 1N4AL3AP2DC270091
 SEDAN 4 DR
 2.5L I4 F DOHC 16V
 GASOLINE
 FRONT WHEEL DRIVE

This CARFAX Report Provided by:
Victory Auto Sales, LLC



No accidents or damage reported to CARFAX



2 Previous owners



At least 1 open recall



7 Service history records



Personal vehicle



156,929 Last reported odometer reading











This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/19/21 at 9:33:20 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.


















Ownership History

The number of owners is estimated

	Owner 1	Owner 2
Year purchased	2013	2014
Type of owner	Personal	Personal
Estimated length of ownership	10 months	6 yrs. 8 mo.
Owned in the following states/provinces	Missouri	Mississippi
Estimated miles driven per year	18,514/yr	20,251/yr
Last reported odometer reading	17,145	156,929

 Title History CARFAX guarantees the information in this section	 Owner 1	 Owner 2
Salvage Junk Rebuilt Fire Flood Hail Lemon	 Guaranteed No Problem	 Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	 Guaranteed No Problem	 Guaranteed No Problem
 GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate		




 Additional History Not all accidents / issues are reported to CARFAX	 Owner 1	 Owner 2
Total Loss No total loss reported to CARFAX.	 No Issues Reported	 No Issues Reported
Structural Damage No structural damage reported to CARFAX.	 No Issues Reported	 No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	 No Issues Reported	 No Issues Reported
Odometer Check No indication of an odometer rollback.	 No Issues Indicated	 No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	 No Issues Reported	 No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Nissan dealer near you to schedule an appointment.	 No Recalls Reported	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

 Detailed History				
Owner 1 Purchased: 2013			Personal Vehicle 18,514 mi/yr	
Date	Mileage	Source	Comments	
04/26/2013		NICB	Vehicle manufactured and shipped to original dealer	
04/30/2013	3	Action Nissan NTAN, LLC Nashville, TN 615-834-3535	Vehicle offered for sale	

actionnissan.com

★ 4.5 / 5.0 [442 Verified Reviews](#) ✓

♥ 3,118 Customer Favorites

05/27/2013		Rick Hill Nissan Dyersburg, TN 731-285-6294 rickhillnissan.com		Vehicle offered for sale
		★ 5.0 / 5.0 40 Verified Reviews ✓		♥ 216 Customer Favorites
08/31/2013	265	Rick Hill Nissan Dyersburg, TN 731-285-6294 rickhillnissan.com		Vehicle sold
		★ 5.0 / 5.0 40 Verified Reviews ✓		♥ 216 Customer Favorites
08/31/2013		Missouri Motor Vehicle Dept.		Vehicle purchase reported - Titled or registered as personal vehicle
08/31/2013		Interstate National Dealer Services Caruthersville, MO inds.com		Service contract issued
09/19/2013		Missouri Motor Vehicle Dept. Caruthersville, MO Title #TMJ58205		Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported
10/18/2013	3,761	Rick Hill Nissan Dyersburg, TN 731-285-6294 rickhillnissan.com		Vehicle serviced - Maintenance inspection completed - Tire condition and pressure checked - Oil and filter changed
		★ 5.0 / 5.0 40 Verified Reviews ✓		♥ 216 Customer Favorites
11/29/2013	6,929	Rick Hill Nissan Dyersburg, TN 731-285-6294 rickhillnissan.com		Vehicle serviced - Maintenance inspection completed - Tire condition and pressure checked - Oil and filter changed
		★ 5.0 / 5.0 40 Verified Reviews ✓		♥ 216 Customer Favorites
01/31/2014	11,256	Rick Hill Nissan Dyersburg, TN 731-285-6294 rickhillnissan.com		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Tires rotated
		★ 5.0 / 5.0 40 Verified Reviews ✓		♥ 216 Customer Favorites
02/17/2014	12,407	Rick Hill Nissan		Vehicle serviced


Dyersburg, TN
731-285-6294
rickhillnissan.com

★ 5.0 / 5.0 [40 Verified Reviews](#) ✓

♥ 216 Customer Favorites



- Maintenance inspection completed
- Front brake pads replaced
- Brake rotor(s) resurfaced
- Tire condition and pressure checked
- Brakes checked

06/25/2014	17,122	Missouri Motor Vehicle Dept. Atwood, CA	Odometer reading reported
07/09/2014		Missouri Motor Vehicle Dept. Atwood, CA Title #TMK30875	Title issued or updated - Vehicle repossessed
07/23/2014		Auto Auction	Vehicle sold - Vehicle offered for sale
			Millions of used vehicles are bought and sold at auction every year.
07/30/2014		Dealer Inventory	Vehicle offered for sale
08/04/2014	17,145	Jim Keras Nissan Memphis, TN 901-373-2800 jimkerasnissan.com/	Vehicle serviced - Body computer/module reprogrammed - Computer reprogrammed
		★ 4.6 / 5.0 233 Verified Reviews ✓	
		♥ 914 Customer Favorites	
08/08/2014		Cordova Automotive, LLC Memphis, TN 901-387-0502	Vehicle serviced - Maintenance inspection completed - Oil and filter changed

Owner 2			Personal Vehicle
Purchased: 2014			20,251 mi/yr
Date	Mileage	Source	Comments
08/12/2014		Mississippi Motor Vehicle Dept.	Vehicle purchase reported
08/29/2014		Mississippi Motor Vehicle Dept. Southaven, MS Title #H03686601	Title issued or updated - New owner reported - Loan or lien reported - Vehicle color noted as White
05/30/2015	37,028	Valvoline Instant Oil Change Southaven, MS 662-393-4426 vioc.com	Vehicle serviced - Fluids checked
		★ 4.6 / 5.0 77 Verified Reviews ✓	

**202 Customer Favorites**

09/14/2015	Mississippi Motor Vehicle Dept. Southaven, MS Title #H036866	Registration issued or renewed - Vehicle color noted as White
01/21/2016	Nissan North America Inc.	Manufacturer Safety recall issued - NHTSA #16V-029 - Recall #PC426 - ALTIMA HOOD LATCH NTB16-011 - Status: Remedy Available Locate an authorized Nissan dealer near you to obtain more information about this recall - Learn more about this recall
<p>Description: On some of the affected vehicles, the secondary hood latch may not function properly.</p> <p>If the primary hood latch is released, the secondary hood latch may not hold the hood closed as designed while the vehicle is in motion. In certain circumstances, this may cause the hood to open while driving and partially obscure the driver's vision, increasing the risk of a crash.</p> <p>Remedy: Your Nissan dealer will replace the hood latch assembly. This repair should take less than an hour to complete and will be offered at no charge for parts and labor. Your dealer may require your vehicle for a longer period of time based upon their work schedule.</p>		
05/23/2016	Nissan North America Inc.	Manufacturer Safety recall issued - NHTSA #16V-244 - Recall #R1609 - MAX ALT RG MUR OCS NTB16-052 - Status: Remedy Available Locate an authorized Nissan dealer near you to obtain more information about this recall - Learn more about this recall
<p>Description: The Occupant Classification System (OCS) is designed to classify the size and weight of the front seat passenger and, under certain conditions, automatically turn OFF the passenger air bag. The OCS system is designed to only deploy the front passenger airbag when the front passenger seat is occupied by an adult. In the affected vehicles, the OCS software may incorrectly classify the passenger seat as empty when it is occupied by an adult. If the OCS does not detect an adult occupant in the passenger seat, the passenger airbag would be deactivated.</p> <p>Failure of the passenger airbag to deploy during a crash (where deployment is warranted) could increase the risk of injury to the passenger.</p> <p>Remedy: The OCS software will be reprogrammed to reduce the potential for classifying the seat as empty. This reprogram will be offered at no charge to the customer and should take less than an hour to complete. Your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.</p>		
12/08/2016	Nissan North America Inc.	Manufacturer Service Campaign issued - Campaign #PC490 - ALT RGE CVT P0776 NTB16-121 - Status: Remedy Available Locate an authorized Nissan dealer near you to obtain more information about this campaign - Learn more about this campaign

Description: Under specific driving conditions, hydraulic pressure may decrease and result in belt slip within the CVT. This may result in MIL illumination. Continuing to drive the vehicle in this condition can lead to accelerated wear and damage to the CVT. Nissan is proactively reprogramming the Transmission Control Module (TCM) with updated CVT software to prevent decreased hydraulic pressure and belt slip from occurring. This is not a safety issue, and the vehicle still meets and/or exceeds all applicable safety standards.

Failure to have this reprogramming performed in a timely manner could result in future damage to your vehicle's transmission. If repair or replacement of the transmission becomes necessary outside of the powertrain warranty period, the resulting repair costs will be at the owner's expense.

Remedy: To assure your continued satisfaction and confidence in your vehicle, and prevent possible future damage to the CVT, your Nissan dealer will reprogram the Transmission Control Module (TCM) at no charge to you for parts or labor. The service should take less than one (1) hour to complete, but your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.

12/22/2016		Mississippi Motor Vehicle Dept. Nesbit, MS Title #H036866	Registration issued or renewed - Vehicle color noted as White
01/17/2018		Mississippi Motor Vehicle Dept. Nesbit, MS Title #H036866	Registration issued or renewed - Loan or lien reported - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as White
01/11/2019		Mississippi Motor Vehicle Dept. Nesbit, MS Title #H036866	Registration issued or renewed - Loan or lien reported - Vehicle color noted as White
02/06/2020		Mississippi Motor Vehicle Dept. Nesbit, MS Title #H036866	Registration issued or renewed - Loan or lien reported - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as White
06/04/2020		Mississippi Motor Vehicle Dept. Hernando, MS Title #H036866	Registration issued or renewed - Loan or lien reported - Vehicle color noted as White
01/15/2021		Mississippi Motor Vehicle Dept. Hernando, MS Title #H036866	Registration issued or renewed - Loan or lien reported - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as White
04/08/2021		Mississippi Motor Vehicle Dept. Hernando, MS Title #H036866	Registration issued or renewed - Loan or lien reported - Vehicle color noted as White
04/29/2021	156,929	Gossett Chrysler Jeep Dodge Memphis, TN	Vehicle offered for sale
06/23/2021		Nissan North America Inc.	Manufacturer Safety recall issued - NHTSA #20V-315 - Recall #R21A6 - ALTIMA HOOD LATCH NTB21-055 - Status: Remedy Available Locate an authorized Nissan dealer near you to obtain more information about this recall - Learn more about this recall

Description: If a vehicle is driven with the primary hood latch disengaged, (and the hood partially opened), the secondary hood latch may become contaminated with dirt or corrosion. If the secondary hood latch is not properly inspected and maintained, such dirt or corrosion could then prevent the secondary hood latch from engaging properly.

If your vehicle is driven with the primary hood latch disengaged (and the hood partially opened), the secondary hood latch on your vehicle may become contaminated with dirt or corrosion. Such dirt or corrosion could then prevent the secondary hood latch from engaging properly. If the primary hood latch is later inadvertently released (such as when refueling the vehicle) and the secondary hood latch, after having been opened, remains stuck in the open position, the hood may open without warning while driving and could obscure the driver's vision, increasing the risk of a crash.

Remedy: A remedy is now available. Dealers will inspect the latch for proper operation, and clean and lube as needed, or replace the secondary latch if it is not fully functional, at no cost to the owner. In addition, dealers will now install a new hood release lever spring and affix an under-hood latch-maintenance warning label to any vehicles affected by this voluntary safety recall campaign. An Owner's Manual addendum card with instructions on how to lubricate and maintain the secondary hood latch will also be mailed together with the customer notification. The repair should take less than one (1) hour to complete. The dealer may require the vehicle for a longer period of time based upon the dealer's work schedule.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Repossession

When a repossession occurs a vehicle owner fails to make loan payments, and the financial institution holding the title takes possession of the vehicle.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved.
7/19/21 9:33:20 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2013 NISSAN ALTIMA vehicle (VIN: 1N4AL3AP2DC270091), which is based on information supplied to CARFAX and available as of 7/19/21 at 10:33 AM (EDT).

Customer Signature

Date

Dealer Signature

Date